## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.








FIG. 1












FIG.7





FIG.8







FIG. 10









FIG. 12










FIG. 17







FIG. 16C









Two-Circuit Unlock Converter Clutch (Disengaged)

FIG. 20




Two-Circuit Lockup Converter Clutch (Engaged)

FIG. 21



Three-Circuit Unlock Mode (Disengaged)

FIG. 22



Three-Circuit Lockup Mode (Engaged)

FIG. 23